

Radon Testing Results for Multifamily Radon Testing

- 4pCi/L and above is considered an action level
- At this time, radon levels at tested locations were considered low and safe for this building.
- ALL RADON TESTS WERE SIGNIFICANLY BELOW 4 pCi/L
- To JOE SAMPLE 2014 Sample Dr. Sample, Ohio 44107

From: Marko E. Vovk (RT259) Ambassador Construction Consultants LLC. 1501 Spring Garden Lakewood, Ohio 44107 216-431- TEST (8378) office 216-924-TEST (8378) cell <u>www.houseinvestigations.com</u> (Radon information and downloads) <u>clevelandmold@aol.com</u> email

RADON RESULTS FOR 2014 Sample Drive, Sample Ohio

- All below 4 pci/l
- Most results were less than 1 pci/l
- Spikes and blanks not included in below data.

	Result		Result		Result		Result
Room #	pCi/L [·]	Room #	pCi/L	Room #	pCi/L	Room #	pCi/L
1543	0.5	540	< 0.3	1046	< 0.3	140	< 0.3
1351	< 0.3	450	< 0.3	1042	< 0.3	B1	1.1
1451	< 0.3	241	< 0.3	940	< 0.3	B2	1.5
1349	< 0.3	245	< 0.3	951	< 0.3		
1141	0.5	140	< 0.3	744	< 0.3	B4	< 0.3
1250	< 0.3	442	< 0.3	641	< 0.3		
1243	0.5	342	< 0.3	549	< 0.3	B3	< 0.3
1140	< 0.3	343	< 0.3	640	< 0.3	849	< 0.3
1141	< 0.3	148	< 0.3	743	0.5	845	< 0.3
				641	< 0.3	849	< 0.3

Results reported above are based on short-term tests and should not be interpreted as annual exposures to the occupants. This is due to environmental and geological as well as changes in the operation of the dwelling.

The U.S. Environmental Protection Agency Recommends that all homes with average indoor radon concentrations of 4 pCi/1 (Pico curies per Liter of air) or higher should be mitigated to reduce the radon levels to below 4 pCi/1. If your results are greater than this level, a determination should be made as to whether to engage in follow-up testing or seek remediation advice.

Ambassador Construction Consultants and personnel do not accept responsibility for the financial or health consequences of the subsequent action taken by the client of their consultants based on these results, nor are we responsible for the results of improper handling of detectors during the exposure period.

Below is the "Multifamily Radon Testing Report". The report was written with the protocol MAMF-2012 ANSI/AAEAR Protocol for conduction radon and radon decay product measurements in multifamily guidelines.

- 8.0 Documentation will be kept in Ambassador Construction Consultants LLC file for a period of six years.
- 8.1 Test Site: 2014 Sample Dr. Sample OhioContacts Donald Duck,
- 8.2.1 Testing service information
- 8.2.2 Marko Vovk from Ambassador Construction Consultants LLC performed all the radon testing in the above said multifamily building. Marko Vovk is licensed in the State of Ohio for radon testing and multifamily radon testing under the licensed number RT259.
- 8.2.3 The laboratory that performed the tests was Air Chek located at 1936 Butler Bridge RD, Mills River, NC 28759. Air Chek is certified in Ohio to perform multifamily radon testing. The Air Chek phone number is 1-828-684-0883, and 1-828-684-8498. The web page is <u>www.radon.com</u>.
- 8.2.4 The State of Ohio radon contact is Chuck McCracken the supervisor for the radon program at <u>chuckMcCracken@odh.ohio.gov</u>. The address is Bureau of Radiation Protection, Ohio Department of Health, 246 N, High Street, 7th floor 35 bldg. Columbus, Ohio 43215. The phone number is 1-614-466-5136
- 8.2.5 Summary of measurement results:
 - No recommendation is needed at this time
 - All radon levels are were low and acceptable.
 - No further testing is needed at this time.
 - All testing, reporting and others were done in accordance with the latest versions of EPA's Home Buyer's and Sellers's Guide to Radon, EPA Citizens Guide to Radon. These can be downloaded at <u>www.houseinvestigations.com</u> or at EPA. Furthermore, all testing was done in accordance to the Multifamily Ohio and EPA guidelines.
 - All tested units with tenants present or not present were provided a copy of the EPA Home buyer's and Sellers Guide to radon dated January 2009. Both above can be downloaded at www.epa.gov/iag.
- 8.5 This report contains all valid measurements.
- 8.5.1 We did not use continues monitors and therefore hourly reading were not taken.
- 8.5.2 We did not average test results. All test results were reported individually.
- 8.5.3 All test results on this report are in picocuries per liter (pCi/L)
- 8.5.4 All quality control measurements have been providing on this report.
- 8.5.5 All prior test data that has been acquired from residents or other testing companies has been incorporated into this report. Below are several first floor tests that were done on July 25, 2013 by Marko Vovk from Ambassador Construction Consultants LLC. After these tests were done, it was determined by management that additional testing was needed to fulfill their multifamily radon testing requirements. This additional testing was the multifamily tests that were done on 10-28-13 which this report reflects. Below is the radon result from the first level that was completed on July 25, 2013.
- 8.6 Detector and location information.

8.6.1 Documentation of all detectors was done by photograph and by diagram drawings. Photographs can be provided if deemed.

Diagram I for testing locations Below are the room #'s and location of the radon tests. Tests were done at identical locations.

ROOMS

 1440
 1543
 1542
 1543
 1351
 1451
 1349
 1141
 1250
 1243
 1141
 1046
 1047
 940
 951
 744

 641
 549
 640
 743
 641
 540
 450
 247
 245
 140
 442
 343
 148
 140
 849
 849
 B1
 B2
 B3
 B4

 CBL1
 CBL2
 CBL3
 CBL4
 Board Room
 Meeting Room
 Janitorial Room
 SP1
 SP2
 SP3




Diagram II for testing locations

Below are the room #'s and location of the radon tests.

Tests were done at identical locations. Red circles show room numbers that were tested on this diagram.

ROOMS


Diagram III for testing location.

This is the floor plan for the first level.

Below are the room #'s and location of the radon tests. Tests were done at identical locations. Red circles show room numbers that were tested on this diagram.


ROOMS

1440 1543 1542 1543 1351 1451 1349 1141 1250 1243 1140 1141 1046 1042 940 951 744 641 549 640 743 641 540 450 241 245 140 442 342 343 148 140 849 845 849 B B2 B3 84 CBL1 CBL2 CBL3 CBL4 Board Room Meeting Room Janitorial Room SP1 SP2 SP3



NOTE:

- The following were the control blanks : CBL1 CBL2 CBL3 CBL4
- The following were the control spikes: SP1 SP2 SP3
- The duplicate controls are listed above and below charts.



- 8.6.1.1 All locations that needed to be tested were tested.
- 8.6.1.2 No detectors were lost during testing
- 8.6.1.2.1 All exact start times and stop times were recorded. We did round up or down for laboratory purposes and to meet the laboratory QA/QC/SOP requirements.

8.6.2 The test device that was used for this project is shown below. The first image is the front of the detector. The second image is the back of the detector.



Description page one of the test detectors	used.
used.	

- 8.6.3 We performed quality control during our testing. Below are the duplicates and blank tests results. (See supporting documentation at end of report for definitions.)
- Green are QA/QC Spike¹ tests (Serial numbers 4726100, 4726101, and 4726104) SPIKE CALUCULTION ATTACHED
- Yellow are Duplicate tests (Rooms 154, 114, 641, and 140) DUPLICATED CALCULATIONS ATTACHED
- Orange are QA/QC Blank tests (Serial numbers 4726147, 4726141, 4726145, 4726139)
- Blue are extra tests from lot in case we had to retest several areas. These extra units were not used and fees were not charged to the client.
- NOTE: All quality control, testing, and calculations meet the OHIO STATE GUIDELINES, RULES, REGULATIONS, LAWS, and Marko Vovk's SOP/QA program.

Below are the laboratory results.

Kit	Start Date	Star t Tim	End Date	End	Te m p	Room	F I O r Result	Varianc e	Analysis	Moisture
Number		е		Time			RADON		Date	Moisture
47261 00	SPIKE						3			
47261										
01	SPIKE						3			
47261 02	2013- 10-28	10: 00 am	2013- 10-30	2:0 0 pm	7 6	1440	3 < 0.3	0.3	2013- 11-01	4.8
47261 <u>03</u>	2013- 10-28	9:0 0 am	2013- 10-30	2:0 0 pm	7 3	1543	3 < 0.3	0.3	2013- 11-01	4.1
47261 04	SPIKE						3			
47261 05	2013- 10-28	9:0 0 am 2:0	2013- 10-30	2:0 0 pm 4:0	7 3	1542	3 < 0.3	0.2	2013- 11-01	4.9
47261 06	2013- 10-28	0 pm	2013- 10-30	0 pm	7 6	CBL1	1 < 0.3	0.4	2013- 11-01	3.4
47261 07	2013- 10-28	9:0 0 am	2013- 10-30	2:0 0 pm	7 3	1543	3 0.5	0.3	2013- 11-01	4.9
47261 08	2013- 10-28	10: 00 am 10:	2013- 10-30	2:0 0 pm 2:0	6 8	1351	3 < 0.3	0.3	2013- 11-01	4.9
47261 09	2013- 10-28	00 am	2013- 10-30	2:0 0 pm	7 2	1451	3 < 0.3	0.3	2013- 11-01	4.9

470/1	2012	10:	2012	2:0					2012	
47261 10	2013- 10-28	00 am	2013- 10-30	0 pm	7 2	1349	3 < 0.3	0.2	2013- 11-01	5.6
47261 11	2013- 10-28	11: 00 am	2013- 10-30	2:0 0 pm	6 9	1141	3 0.5	0.2	2013- 11-01	4.9
47261 12	2013- 10-28	10: 00 am 11:	2013- 10-30	2:0 0 pm 2:0	6 8	1250	3 < 0.3	0.2	2013- 11-01	4.9
47261 13	2013- 10-28	00 am 11:	2013- 10-30	2:0 0 pm 2:0	7 0	1243	3 0.5	0.3	2013- 11-01	4.9
47261 14	2013- 10-28	00 am 11:	2013- 10-30	0 pm 2:0	6 9	1140	3 < 0.3	0.2	2013- 11-01	5.6
47261 15	2013- 10-28	00 am 11:	2013- 10-30	0 pm 2:0	7 0	1141	3 < 0.3	0.2	2013- 11-01	4.8
47261 16	2013- 10-28	00 am 11:	2013- 10-30	0 pm 2:0	7 1	1046	3 < 0.3	0.2	2013- 11-01	4.8
47261 17	2013- 10-28	00 am 11:	2013- 10-30	0 pm 2:0	6 9	1042	3 < 0.3	0.2	2013- 11-01	5.6
47261 18	2013- 10-28	00 am 11:	2013- 10-30	0 pm 2:0	7 3	940	3 < 0.3	0.2	2013- 11-01	5.6
47261 19	2013- 10-28	00 am 12:	2013- 10-30	0 pm 2:0	7 3	951	3 < 0.3	0.2	2013- 11-01	5.6
47261 20	2013- 10-28	00 pm 12:	2013- 10-30	0 pm 3:0	7 1	744	3 < 0.3	0.3	2013- 11-01	4.2
47261 21	2013- 10-28	00 pm 12:	2013- 10-30	0 pm 3:0	7 1	641	3 < 0.3	0.3	2013- 11-01	5.6
47261 22	2013- 10-28	00 pm 12:	2013- 10-30	0 pm 2:0	6 8	549	3 < 0.3	0.2	2013- 11-01	5.5
47261 23	2013- 10-28	00 pm 12:	2013- 10-30	0 pm 2:0	7 2	640 743	3 < 0.3	0.3	2013- 11-01	4.9
47261 24	2013- 10-28	00 pm 12:	2013- 10-30	0 pm <u>3:0</u>	7 1	,	3 0.5	0.2	2013- 11-01	3.4
47261 25	2013- 10-28	00 pm 12:	2013- 10-30	0 pm 3:0	7 1	641	3 < 0.3	0.2	2013- 11-01	6.9
47261 26	2013- 10-28	00 pm 1:0	2013- 10-30	0 pm 3:0	6 7	540	3 < 0.3	0.3	2013- 11-01	4.8
47261 27	2013- 10-28	0 pm 1:0	2013- 10-30	0 pm 3:0	7 3	450	3 < 0.3	0.3	2013- 11-01	4.2
47261 28	2013- 10-28	0 pm	2013- 10-30	0 pm	6 8	241	2 < 0.3	0.3	2013- 11-01	4.9

		1:0		3:0						
47261 29	2013- 10-28	0 pm	2013- 10-30	0 pm	7 3	245	2 < 0.3	0.3	2013- 11-01	4.9
47261	2013-	1:0 0	2013-	3:0 0	7				2013-	
30	10-28	pm	10-30	pm	, 1	140	1 < 0.3	0.2		4.9
47261	2013-	12: 00	2013-	3:0 0	6				2013-	
31	10-28	pm 1:0	10-30	pm 3:0	8	442	3 < 0.3	0.3	11-01	5.6
47261	2013-	0	2013-	0	6				2013-	
32	10-28	pm 1:0	10-30	pm 3:0	9	342	3 < 0.3	0.3	11-01	4.9
47261 33	2013- 10-28	0 pm	2013- 10-30	0 pm	7 5	343	3 < 0.3	0.3	2013- 11-01	4.2
		1:0		3:0		545	5 < 0.5	0.5		4.2
47261 34	2013- 10-28	0 pm	2013- 10-30	0 pm	7 1	148	1 < 0.3	0.2	2013- 11-01	4.9
47261	2013-	1:0 0	2013-	3:0 0	7				2013-	
35	10-28	pm	10-30	pm	, 1	140	1 < 0.3	0.2	11-01	4.9
47261	2013-	1:0 0	2013-	3:0 0	6				2013-	
36	10-28	pm 2:0	10-30	pm 4:0	9	B1	0 1.1	0.3	11-01	5.7
47261	2013-	0	2013-	0	7				2013-	
37	10-28	pm 1:0	10-30	pm 3:0	0	CBL3	1 < 0.3	0.3	11-01	3.5
47261 38	2013- 10-28	0 pm	2013- 10-30	0 pm	6 5	B2	1 1.5	0.2	2013- 11-01	5.6
47261	10-20	рш	10-30	рш	J	DZ		0.2	11-01	5.0
39		2:0		4:0			3			
47261 40	2013- 10-28	0 pm	2013- 10-30	0 pm	6 7	B4	1 < 0.3	0.3	2013- 11-01	4.2
47261	10 20	PIII	10 00	PIII	,			0.0		1.2
41		1:0		3:0			3			
47261 42	2013- 10-28	0 pm	2013- 10-30	0 pm	6 4	B3	1 < 0.3	0.2	2013- 11-01	5.6
		2:0		4:0		20		0.2		0.0
47261 43	2013- 10-28	0 pm	2013- 10-30	0 pm	7 6	849	3 < 0.3	0.3	2013- 11-01	4.9
47261	2013-	2:0 0	2013-	4:0 0	7				2013-	
44	10-28	pm	10-30	pm	0	CBL2	1 < 0.3	0.3	11-01	3.5
47261 45										
47261	2013-	12: 00	2013-	2:0 0	6				2013-	
46	10-28	pm	10-30	pm	7	845	3 < 0.3	0.2	11-01	5.6
47261 47							3			
47261	2013-	2:0 0	2013-	4:0 0	6				2013-	
48	10-28	pm	10-30	pm	9	849 CRL 4	3 < 0.3	0.2	11-01	4.9
47261	2013-	2:0	2013-	4:0	7	CBL4	1 < 0.3	0.3	2013-	4.2

8.7 Test Conditions


8.7.1 Protocol Conditions

- No observed non-compliance with or deviations from required conditions.
- Closed-building conditions prior to and during the test period. We have photos of each unit tested before and after.
- No deviations from normal occupied temperature.
- No changes in the detector placement, no seals altered, and no test interfered. We have photos of all tests at start and at finish. Photos can be made available if deemed.
- No observed anomalies.
- No unusual or severe weather conditions during the radon testing.
- 8.7.2 Non-interference controls
 - We taped all radon tests to a center non masonry drywall wall partitions. The tape and test were photographed before and after. No tests were tampered with.
 - All tenants signed the noninterference agreement with exception of two tenants who were gone or out of town.
 - Many units were vacant or unoccupied and nobody was present to sign the noninterference agreement. We did tape the agreement to the wall just in case someone would sign it. We have photos of all rooms tested and all noncompliance agreements in our files. These can be made available if deemed. Below are all the signed noninterference agreements with unit numbers. The address on these was all the same so we wrote Westerly III for all addresses.

<section-header>OCUPANT / TENANT / HOME OWNER DACUPANT / TENANT / HOME OWNER MILLINGS INTO ANY ANY ANY ANY ANY ANY ANY ANY ANY ANY</section-header>		OCUPANT TENANT HOME OWNER DELEGES SINK BOTH COPIES (Below) ARRESIGNED ON COPIES (Below) Research of the second strategy of the second strategy in the second strategy of the second str
<section-header><section-header><section-header></section-header></section-header></section-header>		
	CULPANT / TENANT / HOME OWNER PLEASE SIGN ROTIC CONSEX ATTAIN MARKEN AND AND AND AND AND AND AND AND AND AN	



If you like to make all above larger, simply cut, paste, and enlarge. Below is a blow up sample.





All tests with exception of the first level had tests locations all the same exact location. We did have to move some wall pictures with tenant permission. All radon tests were taped to the wall, all location were measured and documented, and all locations were photographed. We can provide the digital photos at some future date if deemed.

- 8.7.3 Mitigation System Status. This section was not applicable.
- 8.7.3 Temporary Conditions.
 - The building was under some renovation.

- Many tested units were vacant. All tested vacant units were heated and windows were closed. No protocol violations were observed in vacant units.
- All bathroom exhaust fans were off, before, during and after radon test.
- No unusual weather or severe storms accrued during the radon testing.
- 8.8 Statement of limitations
 - There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations. Variations may be due to changes in the weather, operation for the dwelling or building, or possible interference with the necessary test conditions.

(We refer radon mitigation and long term testing to Radon Survey System Inc. at 330-963-6633). Ambassador Construction Consultants and personnel does not accept responsibility for the financial or health consequences of the subsequent action taken by the client of their consultants based on these results, nor are we responsible for the results of improper handling of detectors during the exposure period.

Please go to our web site www.houseinvestigations.com for additional radon information (We refer Radon Mitigation and long term testing to Radon Survey System Inc. at 330-963-6633).

Thank you Ambassador Construction Consultants 216-924-8378 Marko E. Vovk T-000259-0 Licensed Radon Tester

End of Multifamily Radon REPORT

Supporting Documents Below

Bowser-Morner Radon Chamber 3 Spikes for QC Chain of Custody.	KAD on TESTSFloor1st2d42d
All Michael Andread Montal Andread All Michael Andread Montal Andread All Michael Andread All Michael Andread All Michael Andread All Michael Andread Biological All Michael Al	CAUTION! RADON TEST IN PROGRESS CLOSED BUILDING CONDITIONS MUST BE MAINTAINED: ALL WINDOW AND DOORS MUST BE CLOSED EXCEPT FOR BRIEF DOOR OPENING FOR ENTRY AND EXIT. HEATING AND AIR CONDITIONING SYSTEMS SHOULD BE OPERATED IN THE AUTO MODE DURING CLOSED BUILDING CONDITIONS. PLEASE CALL NUMBER BELOW FOR ADDITIONAL INFORMATION CONCERNING TESTING OF THIS BUILDING
Door sign unused. All rooms tested received door	Ambassador Construction Consultants LLC Marko Vovk # RT259 216-924-8378] Radon sign used. These were all taped to the wall and posted next to all radon tests. Additional signs were left on kitchen countertops.

10		SPIKE DATA IS IN AMBASSADOR FILE
~	NUDANT / TENANT / LIOME OWINED	
-	CUPANT / TENANT / HOME OWNER	
PL	EASE SIGN BOTH COPIES (Below)	
	BASSADOR CONSTRUCTION CONSULTANTS LLC MARKO VOVK RADON TESTING 1501 SPRING GARDEN AVE, LAKEWOOD OHIO 44107 Clevelandmold@aol.com email www.houselvestigations.com website radon videos on youtube simply Goggle ClevelandMarko	
	Residential Testing Program	
	(Get 2 signed copies, 1 to keep and 1 for the client)	
DAD	OON INSPECTION DECLARATION OF VOLUNTARY COMPLIANCE	
As the and Sei	responsible party for the residence listed below. I hereby acknowledge receipt of the EPA's "Home Buyer's ller's Guide to Radon". I further understand that potential purchasers and/or lenders will be making and decisions pending the outcome of this test. Given this information I hereby certify that:	
(1)	I agree to keep this house closed (except for normal entry and exit) for at least 12 hours prior to the start of the test.	
(2)	I agree to keep all doors and windows shut during the entire test period except for normal entry and exit.	
(3)	I will not knowingly alter the test environment in any way including, but not limited to, raising or lowering the thermostat(s) or changing HVAC fan controls, or moving the test device(s).	
(4)	I will not touch, tamper with, remove, cover, or change the location of the test device(s).	
(5)	I will report any circumstances that occur during the test that may influence the final results such as unusual or severe weather, power outages, etc.	
(6)	If I have any questions about the test I will contact the testing firm immediately. <telephone></telephone>	
	TEST ADDRESS	
	ant or Responsible Party X	
Occup		
	Address Date	
	Address Date Technician Marko Vovk (216-924-8378) Clevelandmold@nol.com	

Chain of Custody

Building Name: Testing Contractor: Marko Vovk 1501 Spring Garden Ave Lakewood Ohio 44107 216-924-8378 Contact Name :

	See Photo	See Photo	See Photo					99 =	СОМ	Place	PU
Serial # Kit	Room	Room	Placement	Start	Start	STOP	STOP End	QA	MENT		
Number	Number	Location	Location Drywall	Date 2013-10-	Time 10:00	End Date 2013-10-	Time 2:00	Floor			
4726102	1440	Living Room	wall Drywall	28 2013-10-	am	30 2013-10-	pm 2:00	14	NA	VOVK	VOVK
4726103	1543	Living Room	wall Drywall	28 2013-10-	9:00 am	30 2013-10-	pm 2:00	15	NA	VOVK	VOVK
4726105	1542	Living Room	wall Drywall	28 2013-10-	9:00 am	30 2013-10-	pm 4:00	15	NA	VOVK	VOVK
4726106	CBL1	BLANK	wall Drywall	28 2013-10-	2:00 pm	30 2013-10-	pm 2:00	99	NA	VOVK	VOVK
4726107	1543	DUPLICATE	wall Drywall	28 2013-10-	9:00 am 10:00	30 2013-10-	pm 2:00	15	NA	VOVK	VOVK
4726108	1351	Living Room	wall Drywall	28 2013-10-	am 10:00	30 2013-10-	pm 2:00	13	NA	VOVK	VOVK
4726109	1451	Living Room	wall	28	am	30	pm	14	NA	VOVK	VOVK

			Drywall	2013-10-	10:00	2013-10-	2:00				
4726110	1349	Living Room	wall Drywall	28 2013-10-	am 11:00	30 2013-10-	pm 2:00	13	NA	VOVK	VOVK
4726111	1141	DUPLICATE	wall Drywall	2013-10- 28 2013-10-	am 10:00	30 2013-10-	pm 2:00	11	NA	VOVK	VOVK
4726112	1250	Living Room	wall Drywall	2013-10- 28 2013-10-	am 11:00	30 2013-10-	pm 2:00	12	NA	VOVK	VOVK
4726113	1243	Living Room	wall	2013-10- 28 2013-10-	am 11:00	30 2013-10-	2:00 pm 2:00	12	NA	VOVK	VOVK
4726114	1140	Living Room	Drywall wall Drawall	2013-10- 28 2013-10-	am 11:00	2013-10- 30 2013-10-	2:00 pm 2:00	11	NA	VOVK	VOVK
4726115	1141	Living Room	Drywall wall Drywall	2013-10- 28 2013-10-	am 11:00	30 2013-10-	2:00 pm 2:00	11	NA	VOVK	VOVK
4726116	1046	Living Room	wall Drywall	2013-10- 28 2013-10-	am 11:00	30 2013-10-	2:00 pm 2:00	10	NA	VOVK	VOVK
4726117	1042	Living Room	wall Drywall	2013-10- 28 2013-10-	am 11:00	30 2013-10-	pm 2:00	10	NA	VOVK	VOVK
4726118	940	Living Room	wall Drywall	2013-10- 28 2013-10-	am 11:00	30 2013-10-	pm 2:00	9	NA	VOVK	VOVK
4726119	951	Living Room	wall Drywall	2013-10- 28 2013-10-	am 12:00	30 2013-10-	pm 2:00	9	NA	VOVK	VOVK
4726120	744	Living Room	wall Drywall	2013-10- 28 2013-10-	pm 12:00	30 2013-10-	pm 3:00	7	NA	VOVK	VOVK
4726121	641	Living Room	wall Drywall	2013-10- 28 2013-10-	pm 12:00	30 2013-10-	pm 3:00	6	NA	VOVK	VOVK
4726122	549	Living Room	wall Drywall	2013-10- 28 2013-10-	pm 12:00	30 2013-10-	pm 2:00	5	NA	VOVK	VOVK
4726123	640	Living Room	wall Drywall	28 2013-10-	pm 12:00	30 2013-10-	pm 2:00	6	NA	VOVK	VOVK
4726124	743	Living Room	wall Drywall	28 2013-10-	pm 12:00	30 2013-10-	pm 3:00	7	NA	VOVK	VOVK
4726125	641	DUPLICATE	wall Drywall	28 2013-10-	pm 12:00	30 2013-10-	pm 3:00	6	NA	VOVK	VOVK
4726126	540	Living Room	wall Drywall	28 2013-10-	pm	30 2013-10-	pm 3:00	5	NA	VOVK	VOVK
4726127	450	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	4	NA	VOVK	VOVK
4726128	241	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	2	NA	VOVK	VOVK
4726129	245	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	2	NA	VOVK	VOVK
4726130	140	DUPLICATE	wall Drywall	28 2013-10-	1:00 pm 12:00	30 2013-10-	pm 3:00	1	NA	VOVK	VOVK
4726131	442	Living Room	wall Drywall	28 2013-10-	pm	30 2013-10-	pm 3:00	4	NA	VOVK	VOVK
4726132	342	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	3	NA	VOVK	VOVK
4726133	343	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	3	NA	VOVK	VOVK
4726134	148	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	1	NA	VOVK	VOVK
4726135	140	Living Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 3:00	1	NA	VOVK	VOVK
4726136	B1	Room	wall	28 2013-10-	1:00 pm	30 2013-10-	pm 4:00	0	NA	VOVK	VOVK
4726137	CBL3	BLANK	BLANK	28 2013-10-	2:00 pm	30 2013-10-	pm 3:00	99	NA	VOVK	VOVK
4726138	B2	Room	Hang Shelf	28 2013-10-	1:00 pm	30 2013-10-	pm 4:00	1	NA	VOVK	VOVK
4726140	B4	Room	Hang Shelf Drywall	28 2013-10-	2:00 pm	30 2013-10-	pm 3:00	1	NA	VOVK	VOVK
4726142	B3	Room	wall Drywall	28 2013-10-	1:00 pm	30 2013-10-	pm 4:00	1	NA	VOVK	VOVK
4726143	849	Living Room	wall	28 2013-10-	2:00 pm	30 2013-10-	pm 4:00	8	NA	VOVK	VOVK
4726144	CBL2	BLANK	BLANK Drywall	28 2013-10-	2:00 pm 12:00	30 2013-10-	pm 2:00	99	NA	VOVK	VOVK
4726146	845	Living Room	wall Drywall	28 2013-10-	pm	30 2013-10-	pm 4:00	8	NA	VOVK	VOVK
4726148	849	Living Room	wall	28 2013-10-	2:00 pm	30 2013-10-	pm 4:00	8	NA	VOVK	VOVK
4726149	CBL4	BLANK	BLANK	28	2:00 pm	30	pm	99	NA	VOVK	VOVK

ASSESSING RESULTS FOR DUPLICATES AND SPIKES

D.1 Assessing Results of Duplicate Quality Control Samples (Precision Measurements)

Measuring radioactive substances, such as radon gas, can be made more difficult due to encounters with random Obstacles. Obstacles met when measuring radon gas with activated charcoal include, but are not limited to, variations of radon at the test location, differences in the test kits, care taken during test kit deployment, and background radiation levels at the laboratory. Therefore, side-by-side radon samples are expected to produce slightly different results. It is critical to understand, document, and monitor your precision error. This knowledge and documentation will allow you to characterize your precision error to clients. Furthermore, the continual monitoring of precision provides a check on every aspect of the measurement system. In order to determine when the differences in side-by-side (duplicate) measurements are larger than expected, EPA recommends calculating and analyzing the relative percent difference (RPD) between the duplicates. The RPD is calculated as the difference between the two samples divided by the average of the two samples. In order to be able to fully assess precision, a minimum of 20 duplicate pairs must be completed.

Figure D-1: Calculating Relative Percent Difference (RPD Calculation for Determining (RPD)

RPD = $|D1-D2| / ((D1+D2) / 2) \times 100\%$ Where RPD = Relative Percent Difference D1 = measured value of the first duplicate D2 = measured value of the second duplicate

RADON LEVEL IN BLUE

		9:0		2:0				
47261	2013-	0	2013-	0	7			
03	10-28	am	10-30	pm	3	1543	3	< 0.3
		9:0		2:0				
47261	2013-	0	2013-	0	7			
07	10-28	am	10-30	pm	3	1543	3	0.5

Relative percent difference calculations can expect larger percent errors for duplicates with less radon than errors for Duplicates exposed to higher radon levels. In order to keep the two ranges in proper perspective, two sets of control Charts have been developed. Since very low radon levels magnify the RPD between samples, it is inappropriate to Calculate the differences for duplicates with averages below 2.0 pCi/L. Therefore, one control chart will be maintained to display and analyze duplicates where the average is between 2.0 and 3.9 pCi/L and a second control chart will be used to assess duplicates averaging 4.0 pCi/L or higher.

47261 11	2013-10-28		2013-10- 30	2:00 pm	69	1141	3	0.5
47261 15	2013- 10-28 11:0	00 am	2013-10- 30	2:00 pm	70	1141	3	< 0.3

Relative percent difference calculations can expect larger percent errors for duplicates with less radon than errors for Duplicates exposed to higher radon levels. In order to keep the two ranges in proper perspective, two sets of control Charts have been developed. Since very low radon levels magnify the RPD between samples, it is inappropriate to Calculate the differences for duplicates with averages below 2.0 pCi/L. Therefore, one control chart will be maintained to display and analyze duplicates where the average is between 2.0 and 3.9 pCi/L and a second control chart will be used to assess duplicates averaging 4.0 pCi/L or higher.

4726121	2013-10- 28	2013-10- 30	3:00 pm	71	641	3	< 0.3	
4726125		2013-10- 30	3:00 pm	71	641	3	< 0.3	
			-					

Relative percent difference calculations can expect larger percent errors for duplicates with less radon than errors for Duplicates exposed to higher radon levels. In order to keep the two ranges in proper perspective, two sets of control Charts have been developed. Since very low radon levels magnify the RPD between samples, it is inappropriate to

Calculate the differences for duplicates with averages below 2.0 pCi/L. Therefore, one control chart will be maintained to display and analyze duplicates where the average is between 2.0 and 3.9 pCi/L and a second control chart will be used to assess duplicates averaging 4.0 pCi/L or higher.

4726130	2013-10- 28		2013-10- 30	3:00 pm	71	140 1	< 0.3
4726135		1:00 pm	2013-10- 30	3:00 pm	71	140 1	< 0.3

Relative percent difference calculations can expect larger percent errors for duplicates with less radon than errors for Duplicates exposed to higher radon levels. In order to keep the two ranges in proper perspective, two sets of control Charts have been developed. Since very low radon levels magnify the RPD between samples, it is inappropriate to Calculate the differences for duplicates with averages below 2.0 pCi/L. Therefore, one control chart will be maintained to display and analyze duplicates where the average is between 2.0 and 3.9 pCi/L and a second control chart will be used to assess duplicates averaging 4.0 pCi/L or higher.

ALL DUPLICATD BELOW 2.0 pCi/L NO FURTHER ACTION NEEDED.

D.2 Assessing Results of Spikes (Monitoring Bias)

To assess the results of spiked measurements over time, the results are plotted on a means control chart. One of the key Elements in spike control charts are to assess the laboratory accuracy over a period. As the quality assurance Program gathers more and more data, control charts will begin to have a higher degree of reliability because more data Will be taken into account. The results of known exposure measurements, or spikes, are plotted on a spike control chart

(Exhibit D-5). The centerline is set at zero, and the warning and control limits are set at +/- 16% and +/- 24% Respectively.

Calculating the Individual Relative Error (IRE)

 $IRE = (MV - TV) / TV \ x \ 100\% \ Where: IRE = Individual \ Relative \ Error \ for \ each \ Measurement \ MV = measured \ value \ for \ the \ spike \ TV = radon \ chamber \ target \ value \ TV= 25.1$


Kit Number	Start Date	Start Time 11:00	End Date	End Time 11:00	Temperature	Result	Variance	%Moisture
4726100	2013-11-01	am 11:00	2013-11-04	am 11:00	70	30.4	0.8	3.4
4726101	2013-11-01	am 11:00	2013-11-04	am 11:00	70	24.1	0.7	3.4
4726104	2013-11-01	am	2013-11-04	am	70	27.3	0.8	3.5

RPD 4726100 = 30.4-25.1 / 25.1 X 100 = 21%

RPD 4726101 = 34.1-25.1 / 25.1 X 100 = 3.5%

RPD 4726104 = 27.3-25.1 / 25.1 X 100 = 8.7%

Figure D-5 Example Control Chart for Plotting Spike Results (> 4.0 pCi/L)



The QA Officer plots the results from the spikes on the appropriate control chart, as results are available, and checks the results as soon as they are plotted. Ideally, the plotting of spike results should show an even distribution of spikes above and below the zero percent (0%) centerline. Radon kits that have been in storage for extended periods may lose Efficiency, resulting in a much greater number of results falling outside the warning level. When results of spikes fall Outside of the warning level, **Marko Vovk** will contact Air Chek immediately.

NO SPIKES IN CONTOL LIMIT. NO FURTHER ACTION NEEDED.

alpha particles that strike the sensor and generate submicroscopic damage called alpha tracks. The damaged portions of the plastic can be made visible by etching in a caustic solution, because the damaged areas are more soluble in caustic than the undamaged plastic. The etched areas can be seen using a microscope. The tracks are typically counted using computer recognition and automated scanning. The number of tracks per unit area is proportional to the integrated average radon concentration in pCi-days/liter. AT's are most commonly used for medium- to long-term tests up to one year in length.

Continuous Monitors

CR and CW – Continuous Radon Monitors and Radon Decay Product Monitors

Continuous monitors use various types of sensors. Some collect air for analysis with a small pump while others allow air to passively diffuse into a sensor chamber. All have electrical circuitry capable of producing and recording integrated radon concentrations for periodic intervals of one hour or less.

Continuous radon monitors measure radon gas. Continuous radon decay product monitors measure radon decay product concentrations and require a pump to sample air containing radon decay products onto a filter assembly.

If a device cannot integrate or record readings each hour or less or is not set to record readings each hour or less, then it is functioning as an integrating device.

Other Devices:

Devices that may be developed that use various other sensors and technologies for integrating data over time. All devices used for measuring radon in buildings shall meet state requirements and be approved by NEHA-NRPP or NRSB. All devices shall be used in strict accordance with manufacturer's instructions.

DEVICE QUALITY CONTROL

Terminology associated with *quality control (QC)* is briefly explained below.

Quality Assurance (QA) and related standard operating procedures are an inherent requirement of any measurement program or project. In lieu of other consensus protocols that may be developed, see EPA Guidance on Quality Assurance (402-R-95-012, October 1997) for details on quality assurance. Additional specific requirements for each device can be found in EPA's "Indoor Radon and Radon Decay Product Measurement Device Protocols." Written

Quality Assurance Plans are required of radon measurement professionals and labs who are state licensed or certified by NEHA-NRPP or NRSB.

Duplicate (Collocated) Measurements

Duplicates are pairs of detectors or monitors deployed in the same location, side-by-side for the same measurement period. The purpose of duplicates is to evaluate precision or agreement between detectors. (Note: Duplicates do not evaluate accuracy; for accuracy, see spiked measurements below.) Duplicates may help identify problems that may introduce error into the test results. Duplicates are typically deployed at a rate of 10% of the measurement locations. When establishing a testing service's overall quality control plan up to fifty duplicates per month are recommended. However, additional duplicate measurement may be required for specific testing programs such as discussed herein for Multifamily buildings.

Field duplicates should provide the same or similar radon results. Duplicate pairs of measurements greater than or equal to 4 pCi/L (148 Bq/m³) should produce a Relative Percent Difference (RPD) greater than 36% no more than 1% of the time. Greater than 1% duplicates above 4 pCi/L (148 Bq/m³) with an RPD greater than 36% indicates the measurement system is "out of control," and all measurements are questionable.

See Appendix C "Definition of Terms" for information on calculating the RPD.

If one duplicate is equal to or greater than 4 pCi/L (148 Bq/m^3) and the other below, the higher result may not be twice or more than the other. Such measurements must be repeated.

Blank Measurements

Blanks are integrating or equilibrating detectors that are not intentionally exposed for sampling (i.e. not left open to permit radon to enter the detector during the deployment period). Blanks help evaluate any detector response from sources other than radon exposure at a testing location such as in the manufacturing process or during shipping, storage, analysis and handling.

Blanks are typically deployed at a rate of 5% of the measurement locations. When establishing a testing service's overall quality control plan, up to 25 blanks per month are recommended.

However, additional blank detectors may be required for a specific testing program such as herein discussed for Multifamily buildings. See Section III, subsection 5.0.

Consult with the manufacturer/laboratory to insure detectorspecific procedures approved by the manufacturer/laboratory are used when conducting blank measurements. For many detectors, blanks are unwrapped and immediately re-

Appendix A: *Informational* Devices and Quality Control

ANSI/AARST MAMF 2012

wrapped (or momentarily opened and closed) to give the appearance that they have been used in testing. The blanks are then shipped with the exposed detectors so that the laboratory cannot distinguish them.

- Laboratory blanks are those returned to the laboratory immediately in order to evaluate laboratory quality yet also serve to evaluate if any unexpected exposures resulted during shipping or handling.
- Office blanks are those that remain in office locations where detectors are stored or handled in order to additionally evaluate any unexpected exposures that might result in those locations. Detectors should be stored and handled in a known low-radon environment.
- *Field blanks* are those that accompany the onsite sampling detectors in order to evaluate any unexpected exposures that might result onsite or from handling procedures.

Since blanks are not exposed, their measurement value should be below the lower limit of detection (LLD—the radon concentration below which the measurement system cannot accurately measure). Depending on the device, if one or more results are greater than the LLD, this may indicate defective detectors, poor quality control or improper procedures. If a problem is identified, the detector supplier should be contacted to evaluate and institute corrective procedures.

Spiked Measurements

Spikes are detectors that have been exposed in a NEHA-NRPP or NRSB approved chamber to a known concentration of radon (i.e. "spiked" with radon). Using spiked measurements can help evaluate the accuracy of a laboratory analysis and/or how accurately detectors supplied by a laboratory measure radon.

Detectors from the same batch as those slated for the sampling program are spiked and returned to the laboratory for analysis as near the sampling period as possible. Many detectors are time sensitive and require return to the laboratory for analysis immediately after spiking. In general, spikes are included at a rate of no less than 3 per 100 sampling locations. When establishing a testing service's overall quality control plan, up to six spikes per month and a minimum of three per year are standard operating procedure. However, a specific testing program such as discussed herein for Multifamily buildings may require additional spiked detectors.

The results from spikes are compared to the known value provided by the reference facility where they are spiked using the formula for Relative Percent Error (RPE). The RPE is plotted on a control chart. If the result of a spike differs greatly from the spike's known concentration, it may

Appendix A: *Informational* Devices and Quality Control

A-3

indicate that the detectors are defective or the laboratory procedures are faulty. EPA 402-R-95-012, *Guidance on Quality Assurance* provides guidance on how to set warning and control limits. In general, the expectation is that the values of RPE fall between $\pm 10\%$ and $\pm 10\%$, but the entire range of $\pm 20\%$ to $\pm 20\%$ is considered "in control." Outside of $\pm -20\%$ but inside $\pm -30\%$ is the warning level and outside of $\pm -30\%$ is the control limit.

See Appendix C "Definition of Terms" for information on calculating Relative Percent Error.

Quality Control for Continuous Monitors

Continuous radon monitors require calibration and background checks within the timeframe recommended and at facilities approved by certification requirements, state licensure requirements or the manufacturer's recommendation, whichever is more stringent. Annual calibrations are commonly a minimum requirement. Crosschecks should be conducted at least every six months. Duplicates using a continuous monitor are to be deployed in 10% of the measurement locations. The agreement of duplicate results are calculated using the RPD as noted above and plotted on control charts. An informal intercomparison with a co-located device that reads in the same units (i.e. pCi/L) can also aid in checking quality.

ANSI/AARST MAMF 2012

THIS IS THE LAST PAGE OF THE REPORT

LAST PAGE